## **TO FIT SIZE CHART**

\*Measurements refer to body size, not garment dimensions



**R036X - POLARTHERM JACKET** 23.02.2016

	XS	S	M	L	XL	2XL	3XL*
Full chest in inches*	34	38	41	44	47	52	54
Full chest in cm*	86,36	96,52	104,14	111,76	119,38	132,08	137,16
German clothing size (men)	44	48	50	54	56	62	64

<sup>\* 3</sup>XL is only available in Black and Navy

HOW TO MEASURE CHEST: Place the tape measure across the back, underneath the arms and then across the fullest part of the chest.

1 Inch = 2,54 cm